

No:	SB 277 -24	Issue:	1
Date:	17/9/24	Sheet:	Page 1 of 1

SUBJECT: Elite 6 / Elite+ Condensation in Headlights

Headlamps have been sent back to the supplier with condensation/water present in the lamps, upon inspection water marks show the rubber cap was not fitted all the way over the ridge which leads to water ingress into the lamps.

If you come across any headlamps with water present, dry the lamp out and ensure the rubber cap is fitted correctly as per Fig. 1.



Fig 1. Ensure that cap is pushed on fully over the ridge.

