

No:	SB212-22		
Date:	10/03/2022	Issue:	No. 1

Subject:	eCollect Speed Warning
-----------------	------------------------

The eCollect has a limited top speed, this speed should not be exceeded. If the top speed is exceeded it raises gearbox temperatures, this in turn can lead to damage within the gearbox.

Warnings have been put in place to inform the driver that they are over speeding and to slow down, if the driver has the warning, they **MUST** slow the vehicle down. If warnings aren't actioned over speeding can cause damage and the operator will be liable for the damage caused.

DE Connect keeps a log of these overspeed events.

A warning symbol as shown in image Fig.1 below will appear and flash in area 4 on image Fig.2, a message stating '**Over speeding slow down**' will be displayed, also a continuous audible warning will be triggered. Please be aware that the warning stays on until it has been below the "off" speed for more than 5s, to prevent it coming on and off.

If the vehicle carries on being driven in an over speed condition initially the torque will be reduced to try and protect the vehicle, if the vehicle carries on the drive system will trip out and the vehicle will need to stop and be restarted to obtain drive. Ultimately this could lead drivers restarting vehicles in dangerous locations.

Fig.1 



Fig.2