

SERVICE BULLETIN			
No:	SB 188-18		
Date:	19/10/18	Issue:	No.

Subject:

Elite 6 Primaax Suspension (double drive) Retaining Bolt Torque Check

Dennis Eagle are asking all operators of Elite 6 trucks fitted with Primaax air suspension (double drive) to check the torque setting of the suspension retaining bolt on the next vehicle inspection and thereafter once every twelve months.

Fig. 1 shows the bolt used on Primaax suspension and the torques figures

The relevant service manual chapters will be amended to reflect this.

NB: Use this bulletin as an update for the Service Manual.

Fig. 1



The bolt pointed out in Fig.1 should be torqued 540-660Nm (398-486 lbf-ft).