

No:

SB 187-18

Date:

19/10/18

Issue:

1

Subject:


Elite 6 Mid Lift Suspension Retaining Bolt Torque Check

Dennis Eagle are asking all operators of Elite 6 trucks fitted with Hendrickson Mid Lift suspension using the spring pivot retaining bolt arrangement shown in Fig. 1 below to check the torque setting on the next vehicle inspection and thereafter once every twelve months.

The relevant service manual chapters will be amended to reflect this.

NB: Use this bulletin as an update for the Service Manual.

Fig.1



The bolt pointed out in Fig. 1 should be torqued 600-700 Nm (443-516 lbf-ft).