

No:

SB196-19

Date:

20/09/19

Issue:

1

Subject:

Elite 6 Volvo Fault Code P061511 – Starter Relay Short to Ground

When investigating Volvo fault code P060511 – Starter Relay Short to Ground, it has come to our attention that the heatshield on the coolant hose near the starter motor has come into contact with a screw on the starter motor relay terminal preventing the vehicle from starting and activating the fault code. The picture below shows the screw (circled) and the correct position of the hose.

